



BREATHE FREELY



The Chartered Society for
Worker Health Protection

Controlling exposures to prevent
occupational lung disease in
MANUFACTURING



Do you
breathe freely?

www.breathefreely.org.uk

Consult the experts and **breathe freely**

At BOHS, we believe that manufacturing employers - managers and supervisors - have a key role to play in minimising health risks. **YOU** can protect your employees by making sure hazards are recognised, risks are evaluated and exposures are effectively controlled.

And we can help you do that by providing the information, resources and signposting to the advice and expertise that we know you sometimes need.



Web-based information hub

A centre of excellence on exposure control.

All our campaign materials are available on

www.breathefreely.org.uk with new ones being added over time to reflect the growing reach of the initiative.



Welder task sheets

We have a series of task sheets which show the controls which need to be in place to protect welders, according to the type of welding, the materials being welded and the nature of the environment where the welding is being carried out.



Welding fume slidepack

There is a slidepack and information sheet for H S & E Managers to use when communicating with their employees about the dangers associated with welding fume.



Guidance materials

We have guidance on LEV, RPE and the hierarchy of control. Over time we will develop a bank of case studies as well as other guidance materials.



External links

Links take you to more detailed guidance and regulations, other sources of relevant information, and to the **BOHS Directory of Occupational Hygiene Services**, which is the definitive list of UK companies able to provide qualified and experienced occupational hygienists, and specialist occupational hygiene support services.